

Accesorios de cobre a soldar

1A Cu

Curva 90°
macho-hembra



Dimensiones	Código	Bolsa / Caja	
12	950112	10/400	
14	950114	10/300	
15	950115	10/300	
16	950116	10/240	
18	950118	10/150	
22	950122	10/100	
28	950128	10/60	
35	950135	5/80	
42	950142	5/40	
54	950154	1/10	

2A Cu

Curva 90°
hembra-hembra



Dimensiones	Código	Bolsa / Caja	
10	950210	10/700	
12	950212	10/500	
14	950214	10/300	
15	950215	10/300	
16	950216	10/200	
18	950218	10/180	
22	950222	10/100	
28	950228	10/60	
35	950235	5/30	
42	950242	5/50	
54	950254	1/10	

40 Cu

Curva 45°
macho-hembra



Dimensiones	Código	Bolsa / Caja	
12	954012	10/600	
14	954014	10/400	
15	954015	10/400	
16	954016	10/500	
18	954018	10/250	
22	954022	10/100	
28	954028	10/80	
35	954035	5/100	
42	954042	5/50	
54	954054	1/10	

41 Cu

Curva 45°
hembra-hembra



Dimensiones	Código	Bolsa / Caja	
10	954110	10/800	
12	954112	10/500	
14	954114	10/400	
15	954115	10/400	
16	954116	10/500	
18	954118	10/200	
22	954122	10/100	
28	954128	10/80	
35	954135	5/100	
42	954142	5/50	
54	954154	1/30	
64	954164	1/20	

85 Cu

Puente
hembra-hembra



Dimensiones	Código	Bolsa / Caja	
12	958512	25/150	
14	958514	10/100	
15	958515	10/180	
16	958516	10/100	
18	958518	10/200	
22	958522	5/100	

86 Cu

semi-puente
macho-hembra



Dimensiones	Código	Bolsa / Caja	
12	958612	10/150	
14	958614	10/150	
15	958615	10/150	
16	958616	10/100	
18	958618	10/100	
22	958622	5/100	

Accesorios de cobre a soldar

90 Cu

Codo 90°
hembra-hembra



Dimensiones	Código	Bolsa / Caja	
10	959010	10/800	
12	959012	10/500	
14	959014	10/400	
15	959015	10/300	
16	959016	10/300	
18	959018	10/200	
22	959022	10/130	
28	959028	10/60	
35	959035	5/40	
42	959042	1/50	
54	959054	1/10	
64	959064	1/25	

92 Cu

Codo 90°
macho-hembra



Dimensiones	Código	Bolsa / Caja	
12	959212	10/400	
14	959214	10/400	
15	959215	10/300	
16	959216	10/300	
18	959218	10/250	
22	959222	10/350	
28	959228	10/60	
35	959235	5/100	
42	959242	5/50	
54	959254	1/10	

130 Cu

Te igual
hembra



Dimensiones	Código	Bolsa / Caja	
10	951310	10/1000	
12	951312	10/400	
14	951314	10/300	
15	951315	10/250	
16	951316	10/200	
18	951318	10/140	
22	951322	10/80	
28	951328	10/40	
35	951335	5/70	
42	951342	5/40	
54	951354	1/10	

130 Cu R

T reducida
hembra



Dimensiones	Código	Bolsa / Caja	
12-15-12	951401	10/300	
14-12-12	951402	10/300	
14-12-14	951403	10/300	
15-12-12	951404	10/250	
15-12-15	951405	10/200	
15-15-12	951406	10/300	
15-18-15	951407	10/300	
15-22-15	951408	10/250	
16-12-14	951409	10/250	
16-12-16	951410	10/250	
16-14-12	951411	10/250	
16-14-14	951412	10/200	
16-14-16	951413	10/200	
18-12-15	951414	10/350	
18-12-16	951415	10/350	
18-12-18	951416	10/250	
18-14-16	951417	10/300	
18-14-18	951418	10/300	
18-15-15	951419	10/180	
18-15-18	951420	10/180	
18-16-16	951421	10/300	
18-16-18	951422	10/300	
18-18-12	951423	10/250	

Resto de gama consultar pág. siguiente.

Accesorios de cobre a soldar

130 Cu R

T reducida
hembra



Dimensiones	Código	Bolsa / Caja	
18-18-15	951424	10/250	
18-18-16	951425	10/300	
18-22-18	951426	10/250	
22-12-22	951427	10/250	
22-14-18	951428	10/200	
22-14-22	951429	10/200	
22-15-15	951430	10/200	
22-15-18	951431	10/200	
22-15-22	951432	10/100	
22-16-22	951433	10/200	
22-18-18	951434	10/150	
22-18-22	951435	10/100	
22-22-12	951436	10/250	
22-22-15	951437	10/250	
22-22-18	951438	10/250	
22-28-22	951439	5/130	
28-12-28	951440	10/200	
28-15-22	951441	10/200	
28-15-28	951442	10/150	
28-18-22	951443	10/150	
28-18-28	951444	10/180	
28-22-22	951445	10/160	
28-22-28	951446	10/130	
28-28-15	951447	10/150	
28-28-18	951448	10/100	
28-28-22	951449	10/130	
35-15-35	951450	5/100	
35-18-35	951451	5/100	
35-22-35	951452	5/80	
35-28-28	951453	5/80	
35-28-35	951454	5/70	
35-35-22	951455	5/70	
42-15-42	951456	5/70	
42-18-42	951457	5/70	
42-22-42	951458	5/60	
42-28-42	951459	5/50	
42-35-42	951460	5/40	
54-22-54	951461	5/20	
54-28-54	951462	5/20	
54-35-54	951463	1/10	
54-42-54	951464	1/10	

240 Cu

Manguito reducción
hembra-hembra



Dimensiones	Código	Bolsa / Caja	
12-10	952401	10/600	
14-12	952402	10/500	
15-12	952403	10/500	
15-14	952404	10/500	
16-12	952405	10/500	
16-15	952406	10/500	
18-12	952407	10/400	
18-14	952408	10/700	
18-15	952409	10/350	
18-16	952410	10/600	
22-12	952411	10/250	
22-15	952412	10/250	
22-16	952413	10/300	
22-18	952414	10/240	
28-15	952415	10/250	
28-18	952416	10/250	
28-22	952417	10/150	
35-18	952418	10/200	
35-22	952419	10/200	
35-28	952420	10/200	
42-22	952421	5/100	
42-28	952422	5/130	
42-35	952423	5/120	
54-28	952424	5/70	
54-35	952425	5/50	
54-42	952426	5/50	
64-54	952427	1/40	

Certificaciones

Accesorios de cobre fabricados según
Norma UNI EN ISO 9002-2000

Accesorios de cobre a soldar

243 Cu

Manguito reducción
macho-hembra



Dimensiones	Código	Bolsa / Caja	
12-10	952501	10/1000	
14-10	952500	10/500	
14-12	952502	10/500	
15-10	952503	10/500	
15-12	952504	10/500	
15-14	952505	10/500	
16-12	952506	10/500	
16-15	952507	10/500	
18-12	952508	10/400	
18-14	952509	10/700	
18-15	952510	10/350	
18-16	952511	10/700	
22-12	952512	10/250	
22-14	952513	10/250	
22-15	952514	10/250	
22-16	952515	10/300	
22-18	952516	10/200	
28-12	952517	10/300	
28-15	952518	10/250	
28-18	952519	10/250	
28-22	952520	10/150	
35-15	952521	10/250	
35-18	952522	10/200	
35-28	952523	10/200	
42-22	952524	5/100	
42-28	952525	5/140	
42-35	952526	5/120	
54-22	952527	5/90	
54-28	952528	5/90	
54-35	952529	5/50	
54-42	952530	5/50	
64-35	952531	1/10	
64-54	952532	1/10	

270 Cu

Manguito unión
hembra-hembra



Dimensiones	Código	Bolsa / Caja	
10	952710	10/500	
12	952712	10/500	
14	952714	10/350	
15	952715	10/300	
16	952716	10/400	
18	952718	10/300	
22	952722	10/200	
28	952728	10/100	
35	952735	10/60	
42	952742	5/100	
54	952754	5/50	
64	952764	5/30	

300 Cu

Manguito reducción
tapón-hembra



Dimensiones	Código	Bolsa / Caja	
10	953010	10/2500	
12	953012	10/1000	
14	953014	10/1000	
15	953015	10/600	
16	953016	10/400	
18	953018	10/500	
22	953022	10/300	
28	953028	10/200	
35	953035	5/100	
42	953042	5/70	
54	953054	5/100	

9

Gel Decapante

Para soldaduras



Contenido	Código	Caja	
100 gr.	DECAPAN	40	

Accesorios de cobre-latón para soldar-roscar

359 GL Cu AP

Racor loco recto
asiento plano sin junta



Dimensiones	Código	⇒	
10x1/2"	851015	100	
12x3/8"	851213	100	
12x1/2"	851215	100	
15x1/2"	851515	100	
15x3/4"	851520	100	
16x1/2"	851615	100	
18x1/2"	851815	100	
18x3/4"	851820	100	
22x3/4"	852220	100	
22x 1"	852225	100	
28x3/4"	852820	100	
28x 1"	852825	50	
35x1¼"	853532	50	
42x1½"	854240	50	
54x 2"	855450	25	

359 GL Cu

Racor loco recto
asiento cónico sin junta



Dimensiones	Código	⇒	
15x1/2"	831515	100	
15x3/4"	831520	100	
16x1/2"	831615	100	
18x1/2"	831815	100	
18x3/4"	831820	100	
22x3/4"	832220	100	
22x 1"	832225	100	
28x3/4"	832820	50	
28x 1"	832825	50	
28x1¼"	832832	50	
35x1¼"	833532	50	
42x1½"	834240	50	
54x2"	835450	25	

2 AG Cu

Racor loco curvo
asiento cónico sin junta



Dimensiones	Código	⇒	
22x3/4"	802220	100	

Juntas de goma para racor loco dos piezas

JUNTAS DE GOMA PARA AGUA Y GAS

Espesor: 3/8" - 1" 2,0 mm.
1¼" - 2" 2,5 mm.



Código	Medida/Diám.ext./int.	⇒	
LJG012	3/8" 14/10	100	
LJG015	1/2" 18/14	100	
LJG020	3/4" 23/18	100	
LJG025	1" 30/24	100	
LJG032	1¼" 37/29	100	
LJG040	1½" 43/37	100	
LJG050	2" 54/45	100	